EAST Search History

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|------|---|---------------------------------|---------------------|---------|------------------|
| L1 | 48 | (US-5907373-\$ or US-5671028-\$ or US-6102545-\$ or US-5701165-\$ or US-5966112-\$ or US-5926293-\$ or US-5709447-\$ or US-5926293-\$ or US-5953469-\$ or US-5418631-\$ or US-5357405-\$ or US-5418631-\$ or US-5430562-\$ or US-5467208-\$ or US-5596429-\$ or US-5845981-\$ or US-5853240-\$ or US-5861990-\$ or US-5926294-\$ or US-5934778-\$ or US-6036329-\$ or US-6038054-\$ or US-6163349-\$ or US-6222689-\$ or US-5212575-\$ or US-5381187-\$).did. or (US-5438453-\$ or US-5506701-\$ or US-5638151-\$ or US-5650867-\$ or US-5659408-\$ or US-5715022-\$ or US-5729315-\$ or US-5784129-\$ or US-5945965-\$ or US-5936751-\$ or US-5945965-\$ or US-5936751-\$ or US-5945965-\$ or US-5936751-\$ or US-5945965-\$ or US-5936751-\$ or US-5945965-\$ or US-592989-\$ or US-4772885-\$ or US-4962347-\$ or US-4975809-\$ or US-5331448-\$ or US-5301046-\$ or US-5331448-\$ or US-5347377-\$ or US-5348828-\$).did. | USPAT | OR | ON | 2006/09/17 11:21 |
| L2 | 2730 | ((349/58).CCLS.) ((349/67).CCLS.) ((349/65).CCLS.) ((349/59).CCLS.) ((349/60).CCLS.) ((D14/371).CCLS.) | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/09/17 11:22 |
| L3 | 2 | 1 and ((hole opening recess indentation gap socket) near5 cover). clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/09/17 11:24 |
| L4 | 3 | 1 and ((hole opening recess indentation gap socket) near5 (panel back housing cover)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/09/17 11:25 |
| L5 | 305 | 2 and ((hole opening recess indentation gap socket) near5 (panel back housing cover)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/09/17 11:25 |
| L6 | 24 | 5 and ((hole opening recess indentation gap socket) near5 (reflect\$5 mirror)).clm. | US-PGPUB; USPAT; EPO; JPO | OR | ON | 2006/09/17 11:25 |